



T101564 - TAIL ROTOR DRIVE 42 DEGREE GEARBOX FIXTURE, RENTAL TOOL, FOR USE ON BELL HELICOPTERS

## Description

# T101564 - TAIL ROTOR DRIVE 42° GEARBOX HOLDING FIXTURE

---

**Condition:** Rental Tool - Not for Sale

**Unit of Sale:** Single Rental

This fixture holds the 42° gearbox quill sleeves from the tail rotor drive system in Bell 205, 212, and 412 aircraft.

The information above is sourced from official Bell Documents, however, we strongly advise consulting manuals or technical documentation for accuracy to ensure the correct tool is used for your specific application.

## Reservation Information

**Rental durations range from as short as one week up to 4 weeks.**

- **Free cancellation up to 15 days prior to your reservation Start date.**
- **If you require a longer rental period, please contact us before reserving to discuss long-term pricing options.**
- **Please view our [Reservation FAQ](#) for more information.**

## PART NUMBER INFORMATION

---

Unpunctuated: T101564

Condition and Unit of Sale

---

**RENTAL TOOL - NOT FOR SALE:** This item is available for rental only and is not for purchase. It is part of our specialized rental tool inventory, designed for temporary use. The tool has been professionally maintained and inspected to ensure optimal performance. Each rental tool undergoes regular servicing to meet high operational standards and is ready for immediate use in your project.

**SINGLE RENTAL:** This is a single rental item available for temporary use. The item has been carefully maintained and inspected to ensure it meets all operational standards. Ideal for short-term projects, this rental tool offers a cost-effective solution without the need for a long-term investment. For proper usage, please refer to the spec sheets and repair manuals associated with this item. Contact us if you have questions about the rental Process, or to arrange a long term rental period.

Date

2025/04/19

Meta Fields

Regular Price : 56.12